ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 12 | Shettihalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0055, W0057, W0051, W0106, W0102, W0059 | NA, Om Shakthi Lyt 8th Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd | ABBIGERE |
| **Segment No.** | **Total Length (m)** | |
| 12/C-W0055/S111917 | 411.63 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 55.26 | 77.525961 | 13.075733 | 77.526465 | 13.075660 | W0059 | W0106 |
| 2 | 210.53 | 77.525902 | 13.075451 | 77.527827 | 13.075206 | W0055 | W0059 |
| 3 | 145.84 | 77.526717 | 13.075937 | 77.525881 | 13.075482 | W0051 | W0055 |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| ASPHALTING TO CROSS AND MAIN ROAD AT ABBIGERE KARIKALLU AREA | 1990000 | 2013 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2013 - 2014 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | ASPHALTING TO CROSS AND MAIN ROAD AT ABBIGERE KARIKALLU AREA | 012-12-000069 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/163/2013-14 | 12/12/2013 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| | | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| KRIDL | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9823734738 | | |

**Zone:** DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0055, W0057, W0051, W0106,

Ravi. N. K.
AE W-12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಜಿ.ಆರ್. ಲೇಔಟ್, ಬಸವೇಶ್ವರನಗರ, ಬೆಂಗಳೂರು

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | n k ravi |

| Date of Inspection | Remarks |
|---|---|
| [redacted]2/2016 | |

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | Location was not determined. |
| Road Condition | | Location was not determined. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|

**Zone:** DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0055, W0057, W0051, W0106,

Ravi N.K. AE W-12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರಾಜರಾಜೇಶ್ವರಿನಗರ, ಬೆಂಗಳೂರು